

## **Test Certificate**



All tests reported herein have been performed in accordance with the laboratory's

Sample Number	Sample Description	Asbestos Result
AS154204	Non-Toxic Crayons (Made in China) Composite of 12 samples	No asbestos detected

## **Sampling Details**

<b>Client Details</b>	Fine Art Supplies			
Sample Date	20 November 2015			
Address P O Box 58-018, Greenmount, Auckland				
Purpose of Sampling	Asbestos ID			
Method Used  Australian Standard: AS 4964-2004, Method used  asbestos in bulk samples			for the identification of	
Accreditation Reg Number	911	Report Version	1	
Sample Team	Client	Analysis by	Stephanie Keer-Keer	

This report must not be altered or reproduced except in full.

**K2** Environmental PO Box 28147 Beckenham Unit 24 105 Bamford Street Woolston 03 384 89 66, 0274 33 78 72 www.k2.co.nz stuart@k2.co.nz

**Approval Key Technical Person** 

13.7. Lee Kee